

## MILLAND RECREATION GROUND Spring Review – March, 2019

Present: Jeremy Parker, Colin Stopher, Rob Findlay, Lorraine Grocott

RoSPA check May 2018 – Overall Medium –

<b>Item</b>	<b>Action</b>	<b>Who</b>
Car park	Good. Drain by shop - monitor for leaves.	
Junior play area	Paint base of posts with preservative	RF
Bollards by hall entrance to field	Need to be cleaned out	RF
Tennis courts (TC)	<ol style="list-style-type: none"> <li>1. Annual check of TC fence uprights. Refer to MTC members to paint in summer. Replacement possibly 5 years = £7K.</li> <li>2. Top rail is needed over the door to the courts.</li> <li>3. Pile of earth at far end of TC to be used to fill in low spots in nearby grassed areas.</li> <li>4. RF to cut back overhanging branches to reduce leaf and acorn fall.</li> </ol>	RF PSmall
Wildlife area for Nursery School	Good.	
Swings surface	Surface to be replaced 2019 – Q. £1700	RF TD
Fencing to residences on left	Fencing to be replaced	
Adventure play area	<ol style="list-style-type: none"> <li>1. Order one load of play bark and rake over.</li> <li>2. Allow 4 sections of top rail of the surround to ability course to be replaced.</li> <li>3. Order 24 carabiners for agility course – chains to be shortened where they have stretched so that they are clear of the ground.</li> </ol>	RF/LG
Basketball unit	<ol style="list-style-type: none"> <li>1. Re-cement crack in concrete.</li> <li>2. New basketball next needed</li> </ol>	RF LG
Yellow climbing frame and surface	De-rust and repaint	RF
Soccer nets	OK for this year – Need ties for net to posts.	LG
Mole Activity	Small amount of activity – by Iping Road	LG
Bonfire site	<ol style="list-style-type: none"> <li>1. Fill in low points on extension to bonfire site.</li> <li>2. Harrow line of new drain and bonfire when conditions permit.</li> <li>3. LG to contact Chiddingfold BG to as how they manage the material allowed onto their site.</li> <li>4. RF to top soil and grass seed site</li> </ol>	RF /LG
Damp course @ rear of hall	Monitor.	RF/LG
BMX at rear of field	<ol style="list-style-type: none"> <li>1. Remove in Spring 19 and soil to be used to level off low area muddy area in SE corner.</li> <li>2. Grip to be cut through hedge line in SE corner to allow water to drain into the ditch on E side of hedge.</li> </ol>	RF
Hedges	<ol style="list-style-type: none"> <li>1. Remove 2 trees on S perimeter.</li> <li>2. Remove car seat in the hedge on S perimeter.</li> <li>3. Cut back buddleia R side of entrance to hall.</li> </ol>	RF
Drain by shop	Monitor and clear as necessary.	RF
Trees around field	Regular agreed check and maintenance.	LG

Flagpole	Good.	LG
Ditches	Clear ditches by 2 oak trees in car perk.	RF
Rights of Way notice board	Frame needs replacing. Matt Cusack to ask for price. LG to obtain new maps.	MC to replace.